UpperRuamahangaMt Bruce SchemeFlood Damage ScheduleFebruary 2004

Site	Damage	Repair	Cost(\$)	Priority	
Ravenstone	Bank erosion 180m	Channel alignment/shingle groynes Planting	12000 2000	M M	
Edwards	Bank erosion 25m	*Willow cabling	2000	М	H - High
Van Barnveld	Bank erosion 120m	*Willow clumps	6000	М	M - Medium
		Channel alignment	3000	Н	wealum
Graham Stuart	Bank erosion 150m with threat of river course change	Major channel realignment	15000	Н	
		Willow clumps *Widening of the narrow section	7000 25000	H H	
Duncan Stuart	Bank erosion 100m with threat of river course change	Channel realignment	16000	Н	
		Willow clumps	8000	М	
Duncan Stuart	Bank erosion 40m	*Willow cabling	2000	М	
McLachlan	Bank erosion	Channel alignment *Rail groynes/Willow clumps	6000 7000	M M	
Te Ore Ore "Crusher"	Bank erosion	*Willow clumps	7000	М	
		Total	118000		
		Amount to be accommodated in the current years programme	16000		
		*Items programmed for the next financial year	49000		
		Net amount	53,000		